

**TURN-IN PROCEDURES FOR
XM107 LONG-RANGE SNIPER RIFLE (LRSR)
REQUIRING CONTRACTOR RETROFIT/UPGRADE**

1

How to Identify the M82, XM107, M107:

- M82 visually has a handle type rail system (shorter rail); M82 is stamped on the receiver
- XM107 has a full rail with rear sight that does not embed into the rail; XM107 may be stamped on the receiver, however a few XM107 weapons have been found with the M82 stamp. (NSN: 1005-01-469-2133, Z05606) Serial Numbers smaller than 7269 are not the correct configuration and must be retrofit.
- M107 LIN (R45351) has full rail with embedded rear sight. (see attachment w/M107 enhancements)

The following offline procedures must be used for returning XM107 Sniper Rifle for contractor (Barrett Manufacturing) retrofit/upgrade IAW MWO 9-1005-239-55-1. If the procedures are not complied with, the retrofit and repair of your weapon(s) will be delayed until required data is provided. Compliance with these procedures is being emphasized to the contractor. Units which do not comply upon request will be reported to the [Provost Marshal](#).

1. Contact **TACOM-RI** first!!! Call Nancy DeBo, ASMST-LC-CSIH, DSN 793-7625, e-mail: debon@ria.army.mil or Anette Flagel, DSN 793-5854 or commercial (309) 782-5854, e-mail: flagela@ria.army.mil .
2. Provide Unit ID, UIC, quantity, POC and Serial Numbers, mode of shipping, (i.e., U.S. Postal, DTS, hand deliver) date weapons are available, date weapons need retrofit/returned to unit. E-Mail to Nancy DeBo or Anette Flagel, debon@ria.army.mil or flagela@ria.army.mil , or Fax to: (309) 782-6016 DSN 793-6016.
3. Prepare documentation: DA Form 2407. Place copies 2 through 5 of DA Form 2407 inside the hard case. E-mail or datafax copy of DA Form 2407 to: debon@ria.army.mil, or flagela@ria.army.mil, fax: DSN 793-6016, commercial (309) 782-6016.
4. For CONUS units and those OCONUS units with access to US Registered Mail Service for both shipping and receiving weapons:
 - a. Contact the Installation Accountable Property Book Officer.

1) The Installation Accountable Property Book Officer will process an **FTE** (Report of Excess) and an **AOE** (Requisition with Exception Data) IAW the Materiel Returns Program as detailed in the Requisition Receipt and Issue System, chapter 7, AR 725-50, 19 Oct 90. The FTE and AOE will be processed offline and may be e-mailed, faxed or phoned in to TACOM-RI. Exception data is serial number of M107, document number of **FTE** and point of contact to include “in-the-clear” shipping address and commercial and/or DSN phone number. E-mail the above transactions to TACOM-RI-SNIPER-REPAIR@RIA.ARMY.MIL (preferred method) or fax to DSN 793-4496 (AMSTA-LC-LEAC, Jan Cadogan).

2) TACOM - ROCK ISLAND will respond with an FTR (reply to report of excess), directing shipment to Barrett Manufacturing, Inc.

3) The weapon will be returned to the unit using the document number from the **AOE, including the DODAAC provided by your Accountability Property Book Officer.**

b. The **FTE** and **AOE** may be phoned into TACOM - ROCK ISLAND, AMSTA-LC-LEAC, Jan Cadogan, DSN 793-4271 or commercial (309) 782-4271 if no fax or e-mail capability is available. E-mail to TACOM-RI-SNIPER-REPAIR@RIA.ARMY.MIL is the preferred method.

5. The above procedures will transfer the accountability of the XM107 LRSR from the unit to the wholesale system. The XM107 LRSR will not be retrofit/repared and returned to the unit unless the above procedures are followed. Regardless of how the weapon is delivered to the contractor, these procedures **must** be followed.
6. Clean weapon and place one empty magazine and scope in the hard case with copies 2 through 5 of DA Form 2407.
7. Shipping Options: **After steps 1-6 have been completed:** (Only return sniper weapon, one empty magazine, and scope and copies 2 through 5 of DA Form 2407, use Barrett Firearms Manufacturing, Inc., DODAAC CMB002, and RIC C8S – Unique Item Tracking (UIT) Reporting is mandatory:
 - a. U.S. Registered Mail – Return Receipt Request - only three weapons may be shipped in one shipment. Mark container with the NSN, Part Number and quantity. Weapons should be shipped overnight when feasible.

Barrett Firearms Manufacturing, Inc.
5929 Miller Lane
Christiana, TN 37037
Commercial Telephone: (615) 896-2938

Authorized Personnel to Receive Shipment:

Mary Scott Smith

- b. DTS – Defense Transportation System – required Category IV transportation Protective Service (TPS) in transit. Weapons returned through DTS shall have the container marked IAW MIL-STD-129, TAC AXHH.
- c. Hand Delivered Weapons – Need pre-approval from TACOM-RI.

After the retrofit/upgrade is completed, the items will be returned to the originating unit. The unit must contact their Installation Accountable Property Book Officer to update weapon information to change the XM107 Z05605 to M107 R45351. **The contractor, Barrett Firearms will place one copy of DA Form 4949 inside the weapon case to assist you in updating weapon information.**

<u>Primary POC:</u> NANCY DEBO AMSTA-LC-CSI-H, DSN 793-7625, commercial (309) 782-7625; fax 6016 E-Mail address: DEBON@RIA.ARMY.MIL	<u>Alternate POC:</u> <u>Weapon System Manager:</u> ANETTE FLAGEL AMSTA-LC-CSI-H, DSN 793-5854 FLAGELA@RIA.ARMY.MIL
<u>TACOM-RI FTE/AOE POCs:</u> AMSTA-LC-LEAC JAN CADOGAN, DSN 793-4271 BETH NICKELL, DSN 793-5415 PAULA RADECH, DSN 793-4928	<u>MWO Coordinator:</u> KATHI JOHNSON AMSTA-LC-LMIM, DSN 793-0684 E-Mail address: JOHNSONK4@RIA.ARMY.MIL
<u>Contract Specialist:</u> BRENDA BOYD AMSTA-LC-CSCC, DSN 793-4066 E-Mail address: BOYDB@RIA.ARMY.MIL	<u>Total Package Fielding:</u> SSG Carolyn Washington-Maybin AMSTA-LC-TPF, DSN 793-7943 E-mail address: Carolyn.washingtonmaybin@us.army.mil
<u>Equipment Specialist:</u> DOUG CARLSTROM AMSTA-LC-CSI-L, DSN 793-2361 E-Mail address: CARLSTROMD@RIA.ARMY.MIL	